



YAMAHA
 NIPPON GAKKI CO., LTD
 P.O. BOX 1, HAMAMATSU, JAPAN

*Combo
 Instruments*

SERVICE NEWS

DX7

YAMAHA & NIPPON GAKKI CO., LTD.
 TECHNICAL DEPARTMENT
 4260 N. CENTRAL EXPRESSWAY
 ANN ARBOR, MI 48106-1500
 TEL 313/761-7155

BULLETIN NO.: E-372

DATE: June, 1986

ROM Part No. Change

[Reason for Change] ROM Part No. has been changed as a result of the ROM manufacturer change. Since the contents of software remain unchanged, the previous (IG114680, Ver. 1.8) and new ROMs are interchangeable.

[Updated ROM]

Part No.	Description
IG114690	ROM Ver. 1.8

[Application to Products]

S/# 131600 and up